

Dukes Heating & Air Conditioning
36601 Newark Blvd #10
Newark, Ca 94560
Phone: 1-510-249-9636
Fax: 1-510-249-9610
Ca.Licence#860923

INVOICE

Invoice Number: 5-29-20-3

Invoice Date:

P.O. Number:

Terms: Net due upon receipt

Payment: Collect upon completion

Bill To: Mr. STARR

9000 Mill Creek Rd
Fremont, Ca

Service Date:

Phone: 656-6887

Jobsite Address: Same

Zone:

Symptom:

No A/C Guest House

Diagnosis:

Airflow & Low Compressor Capacity. NOT STARTING, FOUND
Mice Nest & 2 mice blocking Capacitor

Repair:

5/29 Pulled & Replace Capacitor with New Dual Capacitor
Test A/C System Working. Refrigerant Pressure is Good
System ok at this time

Parts and Services

Item Number	Description	Price
1	DUAL CAP	\$ 78.50
	100 DISC	\$ - 78.50
		\$ 70.65
	TA	\$ 6.59
	L HORN	\$ 150 -
		\$
		\$
		\$
		\$

The services as described above have been authorized and/or approved.

I understand the warranty terms and conditions, as they have been explained to me. My payment is for the billable services rendered for this service.

Check/Cash: 3207 \$ 227.19

Accepted

Subtotal: \$

Tax: 9.75% \$

Total: \$ 227.19

Thank You

Duke

Service Technician

Paid 5/29/2020 Chk#3207